	Property is: Single Fan	nily 🗹	Duplex	☐ Other ☐	
Date:	7/19/2011	illy 🗀	Duplex		
take no respo	nsibility for problems discovered	after the ins	pection dat	. The City of Milwaukee, the Redevelopment Author e, or for omissions through error or oversight. The li eral Block Grant or HOME programs.	
Exterior C	Condition Report				
Location	Required Work			Note/Comments	Cost
Site	Landscaping	n/a 🗌	Yes 🔽	Self Help (remove trees and brush)	\$ 500.00
	Steps/Handrails	n/a ∐	Yes ✓	7 riser front service walk w/rail	\$ 987.00
	Service walks	n/a ✓	Yes 🗌		\$
	Fencing	n/a ✓	Yes 🗆		\$
	Parking	n/a ✓	Yes 🗌		\$
	Retaining walls	n/a 🗸	Yes 🗌		\$
	Other	n/a 🔲	Yes 🗆		\$
	Other	n/a 🗌	Yes 🗌		\$
Garage	Singles: repair	n/a □	Yes 🗌		\$
N/A	Shingles: Roof over existing	n/a \square	Yes 🗆		\$
14/24	Shingles:Tear off & re-roof	n/a \square	Yes 🗆		\$
	Gutters/downspouts	n/a \square	Yes 🗆		\$
	Flashing	n/a \square	Yes 🗆		\$
	Eaves	n/a 🗌	Yes 🗆		\$
	Siding	n/a 🗌	Yes 🗌		\$
	Doors	n/a 🗌	Yes 🗌		\$
	Windows	n/a 🗌	Yes 🗌		\$
	Slab	n/a 🗌	Yes 🗌		\$
	Paint	n/a 🗌	Yes 🗌		\$
	Electrical	n/a 🗌	Yes 🗌		\$
	Other	n/a □	Yes 🗌		\$
Porches	Roof	n/a 🗌	Yes 🗸	part of main house	\$
	Deck-upper	n/a ☑	Yes 🗌	part of main nouse	\$
	Decklower	n/a 🗌	Yes 🗸	complete	\$ 2,880.00
	Steps/handrails	n/a \square	Yes ☑	rear	\$ 375.00
	Ceiling	n/a ☑	Yes 🗌	1001	\$ 373.50
	Guardrails	n/a ☑	Yes 🗆		\$
	Structural	n/a ✓	Yes 🗌		\$ \$
	Paint		Yes \square		\$

n/a ☐ Yes ☐

Other

\$

House

Chimney	n/a ☑ Yes □		\$	
Shingles: repair	n/a ☑ Yes 🗆		\$	
Shingles: Roof over existing	n/a ☑ Yes 🗆		\$	
Shingles:Tear off & re-roof	n/a ☐ Yes ☑		\$	8,720.00
Gutters/downspouts	n/a ☐ Yes ☑		\$	1,008.00
Flashing	n/a ☐ Yes ☑		\$	250.00
Eaves	n/a ☐ Yes ☑		\$	756.00
Siding	n/a ☑ Yes 🗆		\$	
Storm Doors	n/a ☐ Yes ☑	front & rear	\$	530.00
Prime ("main") Doors	n/a ☐ Yes ☑	front & rear	\$	700.00
Storm Windows	n/a ☐ Yes ☑		12 \$	1,200.00
Prime ("main") Windows	n/a ☑ Yes □		\$	
Paint	n/a ☐ Yes ☑	complete	\$	1,080.00
Foundation	n/a ☑ Yes 🗆		\$	
Electrical	n/a ☑ Yes 🗆		\$	
Other	n/a □ Yes □		\$	
Other	n/a □ Yes □		\$	
Other	n/a 🗌 Yes 🗀		\$	
Other	n/a ☐ Yes ☐		\$	

Exterior: Estimated Cost:* \$ 18,986.00

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report						
	Unit: Entire unit (single family) Upper unit of duplex	✓				Lower unit of duplex Other	
Mechanical Heating	Required Work						
	Repair/replace boiler	n/a	4	Yes			\$
	Repair radiation	n/a	4	Yes			\$
	Repair/replace furnace	n/a	√	Yes			\$
	Repair ductwork	n/a	1	Yes			\$
	Replace thermostat	n/a		Yes	V		\$ 100.00
	Repair/replace grilles	n/a	1	Yes			\$
Electrical	Tune boiler/furn. insp ht exchange	en/a	√	Yes			\$
Electrical	Repair/replace receptacles	n/a	7	Yes			\$
	Repair/replace switches	n/a	1	Yes			\$
	Repair/replace fixtures	n/a	√	Yes			\$
	Install outlets and circuits	n/a	1	Yes			\$
	Install outlets and circuits	n/a	4	Yes			\$
	Install outlets and circuits	n/a	1	Yes			\$
	Install outlets and circuits	n/a	√	Yes			\$
	Upgrade service	n/a	1	Yes			\$
	Other	n/a		Yes	4	make all circuits safe	\$ 1,000.00
Di ali	Other	n/a		Yes	4	add GFIC as required by code	\$ 400.00
Plumbing	Repair/replace kitchen sink	n/a		Yes	V		\$ 519.00
	Repair/replace kitchen sink fauce	n/a		Yes	V		\$ 315.00
	Repair/replace tub	n/a	1	Yes			\$
	Repair/replace tub faucet	n/a		Yes	4		\$ 175.00
	Repair/replace toilet	n/a		Yes	4		\$ 298.00
	Repair/replace lavatory	n/a	4	Yes			\$
	Repair/replace lavatory faucet	n/a		Yes	4		\$ 134.00
	Repair/replace wash tub	n/a	1	Yes			\$
	Repair/replace wash tub faucet	n/a	1	Yes			\$
	Unclog piping:	n/a		Yes	4		\$ 115.00
	Repair drain/waste/vent piping	n/a		Yes	4		\$ 220.00
	Repair water piping	n/a		Yes	4		\$ 309.00
	Repair/replace water heater	n/a	7	Yes			\$
	Other	n/a		Yes			\$
	Other	n/a		Yes			\$

Windows								
	Replace broken glass	n/a	V	Yes			\$	
	Repair or replace sash	n/a		Yes	V		24 \$	1,800.00
Doors	Repair or replace doors	n/a		Yes	7		\$	
	Repair or repl. locks/latches		<u> </u>	Yes		Self Help	\$	
Walls/Ceiling	gs Repair or repl. @ defective	n/a		Yes	4		\$	1,416.00
Paint	Repair or repl. @ defective	n/a	П	Yes	7		\$	320.00
Fire Safety							·	
	Install smoke/CO alarm:bsmt.	n/a		Yes	√	Self Help	\$	40.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	V	Self Help	\$	40.00
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	V	Self Help	\$	40.00
Handrails	Repair/replace defective	n/a	V	Yes		Self Help	\$	
Stairs	Repair defective	n/a		Yes	7	basement	\$	864.00
Floors	Repair defective	n/a	[J]	Yes			\$	
Other	riopan derestive	π/α	<u> </u>	100			Ψ	
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
						Interior: Estimated Cost:	\$	8,105.00
						Total Exterior and Interior Cost:*	\$	27,091.00

Inspected by: Chris Buzzell Date: 07/19/2011

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.